

# LIST OF SUPPLIES REQUIRED FOR NON-DESTRUCTIVE TESTING

List of Supplies:	(Approx. Cost)
1. Coveralls	\$ 60.00
2. Lab Coat	\$ 30.00
3. Safety glasses	\$ 10.00
4. Latex gloves ( <b>Box of 100</b> ) ( <b>5 boxes</b> )	\$ 50.00
5. Leather work gloves ( 3 PR)	\$ 15.00
6. Welding Gloves	\$ 15.00
7. Calculator (Scientific)	\$ 15.00
8. 6" ruler	\$ 5.00
9. Red Pens (1 pk)	\$ 10.00
10. HB#2 Pencils (1 pk)	\$ 5.00
11. Magnifying Glass	\$ 10.00
12. Cloth Ruler	\$ 5.00
13. Flashlight	\$ 10.00
13. Safety Shoes – CSA approved, Green triangle/Grade/as per 2195-02 (Required for classroom/shop environments) 100% time	\$100.00
14. Half Mask with Hepa Filter (Available at the Campus)	\$ <u>35.00</u>
<b>Total \$375.00</b>	